CONTENTS

Page

SECTION 1 -WELDING MATERIALS. 1-1

Mild Steel-Arc-AWS/ASTME-6011 1-1
Mild Steel-Arc-AWS/ASTME-6012 1-2
Steel -Arc(low-alloy or mild) -AWS/ASTM E-7018 1-3
Steel - Arc (low-alloy, high-strength steels) - AWS/ASTM E-11018 1-4
Steel -GMA(low- to medium-carbon) -AWS/ASTME-70 S-3, or S-6 1-5
Steel -Torch or GTA(low- and medium-carbon) 1-7
Brazing -Torch (flux-coated rod for general brazing) 1-8
Steel 1-9
Brazing -Torch (flux-coated rod for high-strength brazing) 1-10
Silver Brazing Kits -Torch 1-11
Cast Iron -Torch (flux-coated rod) 1-11
Cast Iron -Arc (fully-machinable nickel base) 1-12
Cast Iron -(fully-machinable) 1-13
Cast Iron -Arc (machinable nickel-iron base) 1-14
Brazing -Arc 1-15
Aluminum -Arc (extruded flux-coated rod) E-4043 1-16
Aluminum -GMA (base spooled wire) E-5356 1-17
Brazing, Gas -Aluminum 1-18
Zinc -Die Cast and Aluminum 1-19

Stainless - Arc (all steels - medium - high carbon, alloy, and tool steels) AWS/ASTM E 312-16 1-20
Buildup -Arc (tungsten, high speed) 1-21
Overlay -Arc (manganese wearfacing) 1-22
Buildup - Arc -tungsten 1-23
Buildup -Arc (FeMn A-Class 3). 1-24
Overlay -Arc (intermediate wearfacing) 1-25
Overlay -Arc (wearfacing - high abrasion) 1-26
Chamfering or Gouging -Arc... 1-27
Graphite (carbon electrodes) 1-28
Solder (tin -lead 50/50) ASTM 50A 1-29
Solder (tin -lead 40/60 -acid core) ASTM 40A 1-29
Solder (tin-lead 60/40-rosincore) 1-30
Solder (tin-silver 96/4) 1-30
Holding and Heat-Resisting Compound 1-32
Surface-Hardening (Case) Compound 1-33
Application Guides and Comparative Index 1-34
Underwater Cutting (Electrode-Underwater Cutting) 1-44

SECTION 2- WEARFACING 2-1
Introduction 2-1
Workpiece Preparation 2-1

Preheat 2-1
Welding on Cast Iron 2-3
Buildup Materials and Base Metals 2-3
Workpiece Positioning 2-4
Thickness of Hard-Facing Deposits 2-4
Types of Wear 2-11
Abrasion 2-11
Impact 2-11
Heat 2-11
Corrosion 2-12
Recommended Amperage and Polarity 2-12
The Difference Between Cross-Checking and Cracking 2-12
Oxy-MAPP Hard-facing 2-13
General Rules 2-13
Flame Adjustments 2-15

EARTH-MOVING AND HEAVY CONSTRUCTION EQUIPMENT 2-16
Tractor Parts and Accessories 2-17
Track Rollers 2-17
Tractor Idlers 2-17
Tractor Rails 2-18
Top Carrier Rolls 2-19

Drive Sprockets 2-20
Tractor Grousers 2-21
Ripper Teeth 2-21
Bulldozer End Bits 2-22
Bulldozer Blades 2-23
Ripper Shanks 2-24
Rock Rake 2-25
Shovel Parts and Accessories.. 2-27
Shovel Rollers 2-28
Shovel Track Pads 2-28
Shovel Idlers 2-29
Shovel Drive Tumblers 2-30
Shovel House Rolls 2-30
Shovel and Dragline Buckets 2-31
Shovel Teeth 2-34
Shovel Bucket Tooth Adapters. 2-35
Shovel Latch Plates 2-37
Shovel Latch Bars 2-38
Shovel Boom Heels 2-39
Cable Sheaves 2-40
Dragline Pins 2-41
Dragline Chains 2-41

Dragline Clevis 2-42
Clamshell Buckets 2-43
Power Shovel Transmissions.. 2-46
Shovel Ring Gears 2-46
Shovel Swing Gears 2-47
Horizontal Travel Gears 2-47
House Rings 2-48
Shafts 2-48
Ditchers and Hole Augers 2-49
Ditcher Drive Segments 2-49
Ditcher Rolls 2-50
Ditcher Drive Sprockets 2-50
Ditcher Teeth 2-51
Post Hole Augers 2-52
Asphalt Mixers and Pavers 2-53
Asphalt Mixer Paddles 2-53
Asphalt Mixer Paddle Shanks 2-54
Paving Machine Paddles 2-54
Paving Agitator Blades 2-55
Paving Screw Conveyors 2-55
Scraper Cutters and Sides 2-56
Scraper Blades 2-57

Page

Grader Blades 2-58
Grader End Bits 2-58
Scooplift Buckets 2-59
Grapple Tines 2-60
Grid Compactors 2-60
Sheepsfoot Tampers 2-61
Curbing Machine Augers 2-63
Backhoe Sidecutters 2-64
Trencher Teeth 2-65
Shredding Hammers 2-66

CRUSHING, GRINDING, AND SCREENING EQUIPMENT. 2-67
Rebuilding and Hard-facing Crusher Roll Shells 2-67
Initial Rebuild and Hard-face of Shells 2-67
General Recommendations 2-67
When to Reapply Hard-facing 2-71
Rebuilding Shells with the Manual Process 2-72
Rebuilding Procedure 2-72
Hard-facing Crusher Shells with the Manual Process 2-72
Welding Techniques 2-73
How to Repair Cracked Manganese Rolls 2-76
Hard-facing Rotor Type Impactors. 2-79

CONTENTS (Continued)

	Page
Rotors and Bars	2-79
Screen Grates	2-79
OTHER QUARRY AND MINING EQUIPMENT	2-80
Crusher Jaws	2-80
Wobbler Feeder	2-80
Crusher Points	2-82
Scalping and Sizing Vibratory Screens	2-82
Gravel Washer Auger Flights	2-83
Log Washer Paddles	2-84
Elevator Bucket Lips	2-84
Quarry Drill Collars and Augers	2-85
SECTION 3 -MOLECULAR METAL	3-1
Introduction	3-1
Components	3-1
ATOMIZED METAL REPAIR COMPOUND (M-41)	3-2
ALLOY GP	3-2
Applications	3-2
Properties	3-2
Directions For Use	3-3
General Information	3-3

Page

ATOMIZED METAL REPAIR COMPOUND (M-42) 3-6
SMOOTHCOAT 3-6
Applications 3-6
Properties 3-6
Directions For Use 3-7
General Information 3-7
ATOMIZED METAL REPAIR COMPOUND (M-43) 3-10
SMOOTHCOAT LIQUID 3-10
Applications 3-10
Properties 3-11
Directions For Use 3-11
General Information 3-12
ATOMIZED METAL REPAIR COMPOUND (M-43) 3-14
RAPIDSTEEL 3-14
Applications 3-14
Properties 3-15
Directions For Use 3-15
General Information 3-16

SECTION 4- MAPP GAS 4-1
Introduction, ... 4-1
Mapp Gas is Safe 4-1

Page

Disadvantages 4-1
Breaktkough in Performance. 4-1
How to Set Up and Use a Welding or Cutting Unit 4-2
  Setting Up 4-2
  Lighting the Torch 4-3
  Extinguishing the Torch 4-3
Welding and Brazing 4-4
  Use of Welding Tips with Mapp Gas 4-4
Fusion Welding 4-5
  Flame Adjustment 4-5
  Carbon Steel Welding 4-7
  Carbon Steel Pipe Welding 4-9
  Cast Iron Welding 4-9
  Aluminum Welding 4-9
  Copper Welding 4-9
Brazing 4-9
Metallizing 4-9
Flame Hardening 4-10
  How Flame Hardening Works.. 4-10
  Carbon Content and Hardness. 4-10
  Quenching 4-10

Page

Flame Hardenable Materials 4-11
Flame Head Design 4-11
How to Flame Cut with Mapp Gas 4-11
Preheat Flame Adjustment 4-12
Oxygen Pressure 4-13
Coupling Distance 4-15
Torch Angle 4-16
Travel Speed 4-17
Nature of the Workpiece 4-17
Tip Size and Style 4-19
Oxygen Supply 4-19
Starting a Cut 4-20
Special Cutting Jobs 4-21
Gouging 4-21
Piercing and Washing 4-22
Cutting Manganese Steel 4-22
Operation Procedures -Bulk Systems 4-24
Start Up Procedure 4-24
Temporary Shutdown Procedure 4-24
Extended Shutdown Procedure. 4-24
The Use of Antifreeze in Flashback Arrestor 4-24
Mapp Gas and Compressed Air Burner 4-25